

dxHeaterCtrl

Fault	Bit	
Charge Fault	4	The high voltage capacitors were failed to reach the desire voltage. Response: Follow Link to Collider Electrical PS Group call in list or Link to Quench Detection Group list
Ground Fault	5	Ground leakage current is about the set point. Response: Follow Link to Collider Electrical PS Group call in list or Link to Quench Detection Group list
Electrical Safety Fault	6	Not wired at the present time. Response: Follow Link to Collider Electrical PS Group call in list or Link to Quench Detection Group list
Reset Node Card	13	
Comm Failure	14	

Note: Bits 13 & 14 are generated by FW and / or SW.

[Link to Collider Electrical PS Group call in list](#)
[Link to Quench Detection Group list](#)